



Alcatel MDR-8000 Transmitters

| Part Number | Frequency | Capacity Key | In stock |
|--------------|--------------|--------------------------|----------|
| 3DH03228AAAA | 10653.75MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03228ADAA | 10588.75MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03228ADAA | 10621.75MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03228ADAA | 10646.25MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03228ADAA | 10653.75 MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03228AEAA | 10795MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03228AFAA | 11365MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03228AFAA | 11365MHz | 3EM01583ABAD 3DS3/64QAM | 1 |
| 3DH03228AGAA | 10588.75MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03228AHAA | 10795MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03236ADAA | 6123.10MHz | 3EM01583ABAD 3DS3/64QAM | 2 |
| 3DH03236ADAA | 6375.14MHz | 3EM01583ABAD 3DS3/64QAM | 2 |
| 3DH03236AFAG | 5795MHz | 3EM01583AAAF 1DS3 64QAM | 1 |

Alcatel MDR-8000 Receivers

| Part Number | Frequency | Capacity Key | In stock |
|--------------|-------------|--------------------------|----------|
| 3DH03132AFAA | 11365MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03132AQAB | 6815MHz | None | 1 |
| 3DH03231AFAA | 10795MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03231AHAA | 10795MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03231AJAA | 11365MHz | 3EM01583ABAC 3DS3/64QAM | 1 |
| 3DH03231AKAA | 10581.25MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03231AKAA | 10653.75MHz | 967-1609-008 8DS1/128TCM | 3 |
| 3DH03231AKAA | 10588.75MHz | 967-1609-008 8DS1/128TCM | 2 |
| 3DH03231AKAA | 10556.25MHz | 967-1609-008 8DS1/128TCM | 1 |
| 3DH03239AFAA | 6375.14MHz | 3EM01583ABAD 3DS3/64QAM | 2 |
| 3DH03239AFAA | 6123.10MHz | 3EM01583ABAD 3DS3/64QAM | 2 |

Wireless Infrastructure Services

1837 California Avenue
 Corona, CA 92881 Ph: (951) 371-4900
 Toll Free: (877) 538-2663
 E-Fax: (951) 848-9092

Web site: www.WirelessInfrastructureServices.com
 Facebook: <https://www.facebook.com/pages/Wireless-Infrastructure-Services/162765600419015>